

ID No. 754	Product/Process Change Notification	Date 05.02.2020
Product	Ordering Code	
ELS61-E Rel.1 MR	L30960N4450A101	
ELS61-E2 Rel.1 MR	L30960N4455A101	
Ordering Code changes:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Product	New Ordering Code	

Reason of Change:

- | | |
|---|--|
| <input type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement | <input type="checkbox"/> Location of production moved |
| <input checked="" type="checkbox"/> Quality improvement | <input type="checkbox"/> Other: |

Description of change:	Introduction of minor modifications on Java embedded platform. The implemented change improves the directory path access check of internal flash file system, which can store application-specific data or data needed for customer Java applications, TLS and OTAP functionality. All changes are not approval relevant and done on application layer only. For identification of improved firmware a new application revision number (ARN: 00.032.02) will be introduced. If there are further questions, our Technical Sales team who offers comprehensive customer support, should be contacted.
Schedule details:	CW/YEAR
Availability of SW for evaluation:	CW07/2020
Availability of modules ex THALES DIS AIS Deutschland warehouse:	CW13/2020
Timing note:	If THALES DIS AIS Deutschland GmbH does not receive a notification to the contrary within a period of 6 weeks, THALES DIS AIS Deutschland GmbH assumes that the customer agrees to the change.

Quality assurance measurements:	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.
--	--

Attachments:

2020/2/11

12.02.2020

X Yang Xue

Product Lifecycle Manager
Signed by: YANG Xue

X *J. Erdmann*

Vice President Quality Management
Signed by: ERDMANN Joerg