

ID No. 595	Product/Process Change Notification	Date 17.09.2018
Product PLS8-E	Ordering Code L30960N3400A300	
Ordering No. changes:	<input type="checkbox"/> Yes <input type="checkbox"/> No	
New Ordering Code:		

Reason of Change:


- | | |
|---|--|
| <input checked="" type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement | <input type="checkbox"/> Location of production moved |
| <input checked="" type="checkbox"/> Quality improvement | <input type="checkbox"/> Other: |

Description of change:	<p>With this PCN an update on the Bd3 RF matching network is introduced, that increases the RF margin in Bd3 for customer applications. To facilitate this the related FW version had to be updated.</p> <p>Further, this new FW enables use of a 2nd source flash memory component.</p> <p>The new FW version identifies itself as:</p> <p>PLS8-E REVISION 03.017 A-REVISION 01.000.09</p> <p>Note, that this FW version MUST NOT be flashed onto modules with production dates earlier than November 2018.</p> <p>The respective approval update document M17-0171-05-TEC.PDF is attached hereto.</p>
Scheduled date of introduction (cw/year):	CW44/2018
Timing note:	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks, Gemalto M2M GmbH assumes that the customer agrees to the change.

Quality assurance measurements:	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.
--	--

17.09.2018

17.09.2018

X 

F.Ryll
PLM

Signiert von: Frank Ryll 10015116

X 

J.Erdmann
VP QM

Signed by: Joerg Erdmann 10015214

Attachments:

- M17-0171-05-TEC.PDF