

ID No. 00599	Product/Process Change Notification	Date 2 October 2018
Product	Ordering Code	
ELS61-USA Rel. 2	L30960N4420A200	
ELS61-USA Rel.2 CI	L30960N4425A200	
Ordering No. changes:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
New Ordering Code:		

Reason of Change:

- | | |
|---|--|
| <input type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement | <input type="checkbox"/> Location of production moved |
| <input checked="" type="checkbox"/> Quality improvement | <input type="checkbox"/> Other: |

Description of change:	<p>Gemalto M2M GmbH is going to introduce a maintenance release to increase the overall system stability of the platform.</p> <p>Following modifications have been implemented:</p> <ul style="list-style-type: none"> - JRC MIDlet updated to allow control of the source port <p>The new application revision string is: SW 02.002 ARN 01.000.03</p> <p>The new JRC is updated to 1.62.02.</p> <p>The existing approvals of applications are not affected.</p> <p>In case of questions about support of previous versions please contact local sales organization.</p>
Scheduled date of introduction (cw/year):	CW51/2018
Timing note:	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks, Gemalto M2M GmbH assumes that the customer agrees to the change.

Quality assurance measurements:	The new version fulfills all internal test requirements according to our Quality Management process and philosophy.
--	---

11/9/2018

09.11.2018

X Peter Shaffer

Peter Shaffer
Product Lifecycle Manager
Signed by: Peter Shaffer 10022570

X 

Jörg Erdmann
Vice President Quality Management
Signed by: Joerg Erdmann 10015214

Attachments:

-