

ID No. 00616	Product/Process Change Notification	Date 6 December 2018
Product	Ordering Code	
ELS61-E Rel. 2	L30960N4450A200	
Ordering No. changes:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
New Ordering Code:		

Reason of Change:

- | | |
|---|--|
| <input type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement | <input type="checkbox"/> Location of production moved |
| <input checked="" type="checkbox"/> Quality improvement | <input type="checkbox"/> Other: |

Description of change:	<p>Gemalto M2M GmbH is going to introduce a maintenance release to improve the overall system performance of the product.</p> <p>Following modifications have been implemented:</p> <ul style="list-style-type: none"> - Improve the HPLMN scan mechanism, then UE can camp to the correct and higher priority PLMN much quicker - Update a parameter to avoid damage caused by unintended current in rare stress test case - improve consecutive call performance <p>FW revision remains the same.</p> <p>In case of questions about support of previous versions please contact local sales organization.</p>
Scheduled date of introduction (cw/year):	CW 4/2019
Timing note:	<p>If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks.</p> <p>Gemalto M2M GmbH assumes that the customer agrees to the change.</p>

Quality assurance measurements:	The new version fulfills all internal test requirements according to our Quality Management process and philosophy.
--	---

17.12.2018

19.12.2018

X Ivonne Krüger

Ivonne Krüger
Product Lifecycle Manager
Signed by: Ivonne Krueger 10015065

X *i. Jörg Erdmann*

Jörg Erdmann
Vice President Quality Management
Signed by: Joerg Erdmann 10015214

Attachments:

-