

ID No. 00478	Product/Process Change Notification	Date 18 April 2018
Product PLS8-X	Ordering Code L30960-N3460-A300	
Ordering No. changes:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
New Ordering Code:	L30960-N3460-B300	

Reason of Change:

- | | |
|--|--|
| <input type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input checked="" type="checkbox"/> Customer requirement | <input type="checkbox"/> Location of production moved |
| <input type="checkbox"/> Quality improvement | <input type="checkbox"/> Other: 2 nd source material |

Description of change:	<p>A configuration change was made to enable newer cryptographic methods such as SHA256. Further, the update routine for OTA DM certificates was improved.</p> <p>This updated configuration will be manufactured from May 2018 onwards.</p> <p>These changes concern application level components only and do not affect the protocol stack.</p> <p>The final, validated update firmware image can be made available via your technical sales representative</p>
Scheduled date of introduction (cw/year):	CW18/2017
Timing note:	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks, Gemalto M2M GmbH assumes that the customer agrees to the change.

Quality assurance measurements:	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.
--	--

19.04.2018

19.04.2018

X *i. Frank Ryll*

Frank Ryll
Product Manager
Signiert von: Frank Ryll 10015116

X *i. Joerg Erdmann*

Jörg Erdmann
Vice President Quality Management
Signed by: Joerg Erdmann 10015214

Attachments:

-