

ID No. 0626	Product/Process Change Notification	Date 21th Feb 2019
Product PLS62_W	Ordering Code L30960N4600A100	
Ordering No. changes:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
New Ordering Code:		

Reason of Change:

- | | |
|---|--|
| <input type="checkbox"/> Technical requirement | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement | <input type="checkbox"/> Location of production moved |
| <input checked="" type="checkbox"/> Quality improvement | <input type="checkbox"/> Other: |

Description of change:	<p>Gemalto M2M GmbH is going to introduce a new FW to improve the overall system performance of the product.</p> <p>Following modifications have been implemented:</p> <ul style="list-style-type: none"> - Change one configuration parameter of the Power Management Unit to avoid component damage caused by unintended current in rare stress test scenario. <p>SW revision remains the same, 02.000.</p> <p>The application revision (ARN) is going to change to 01.000.03</p> <p>This change is not approval relevant. No functionality impact of product.</p>
Scheduled date of introduction (cw/year):	CW10 2019, rely on production plan
Timing note:	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks, Gemalto M2M GmbH assumes that the customer agrees to the change.

Quality assurance measurements:	The new version fulfils all internal test requirements according to our Quality Management process and philosophy.
--	--

Attachments:

2019/2/21

22.02.2019

X Yang Xue

Yang Xue
Product Lifecycle Management
Signed by: Xue Yang 10031953

X 

Jörg Erdmann
Vice President Quality Management
Signed by: Joerg Erdmann 10015214