

ID No. 00579	<b>Product/Process Change Notification</b>	Date 3 <sup>rd</sup> September 2018
<b>Product</b>	<b>Ordering Code</b>	
<b>BGS2-E Rel.4</b>	<b>L30960N2200A400</b>	
<b>BGS2-W Rel.4</b>	<b>L30960N2210A400</b>	
Ordering No. changes:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
New Ordering Code:		

**Reason of Change:**

- |   |  |
|---|--|
| <input type="checkbox"/> Technical requirement          | <input type="checkbox"/> Change of production process/logistical changes |
| <input type="checkbox"/> Customer requirement           | <input type="checkbox"/> Location of production moved                    |
| <input checked="" type="checkbox"/> Quality improvement | <input type="checkbox"/> Other:  |

<b>Description of change:</b>	Gemalto introduce with this release following improvements: - Bearer Independent Protocol capability - HTTP post session behaviour - several minor modifications to improve the overall system stability  The new software can be identified by ARN 01.000.22.  In addition Gemalto has modified the average ramp-down rate in soldering profile in updated HID valid for all BGS2 variants.  For details on all changes please refer to corresponding RN.
<b>Scheduled date of introduction (cw/year):</b>	Cw42 2018 RN, documentation and software are available upon request.
<b>Timing note:</b>	If Gemalto M2M GmbH does not receive a notification to the contrary within a period of 6 weeks, Gemalto M2M GmbH assumes that the customer agrees to the change.

<b>Quality assurance measurements:</b>	The new version fulfills all internal test requirements according to our Quality Management process and philosophy.
--	---

03.09.2018

03.09.2018

X *i.v. Armin Dimai*

Armin Dimai  
Product Lifecycle Manager IoT  
Signed by: Armin Dimai 10015210

X *i. Jörg Erdmann*

Jörg Erdmann  
Vice President Quality management IoT  
Signed by: Joerg Erdmann 10015214

**Attachments:**

-